9th point :- 2

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

To the Asst Executive Engineer
BBMP
Dasarahalli Sub Division
Sampangi Ramaiah Layout

Date : 26.5.2014

1. Name of the Customer —
a) Village Ward No:- 14 4th cross b) Block / Taluk. — c) District Bangalore
2. Location. —
3. Lithology of the Area Granetic in nature
4. Tophographic Features of the Area The area was a plain land
5. Hydrogeological condition of the Area Good
6. Geophysical survey result. By Divining method
   a) Type of Method. —
   b) No of Soundings Conducted. —
   c) Recommended Sounding. —
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 450' } 2
      660 - 700' }
      880 - 930' }
      2
   e) Condition of Ground Water. Good
7. Type of well Recommended. Borewell (6½") —
8. Depth Recommended. 950 - 1000' —
9. Expected Yield. 1300 - 1500 GPH —
10. Quality of Water. Good —
11. Approximate depth at which the water is expected to be met. Around 450' —
12. Recommended Type and Length of casing to be inserted. Nearly 150 - 180' of MS casing may be needed —
13. Rain water Harvesting adviced or not Strictly Adviced —
14. Remarks. Recommended points for Drilling

ಕಾರ್ಯನಿರ್ವಾಹಕ ಎಂಜಿನಿಯರ್ ಅವರ ಕಛೇರಿ
ಉ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಶಾಂತಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073

Site Plan Map



Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

10th point :-

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

To the Asst Executive Engineer
BBMP
Dasarahalli Sub Division.

Date : 26.5.2014

1. Name of the Customer

a) Village Ward No 14 4th Cross b) Block / Taluk. Shoshadri nagar c) District Bangalore

2. Location.

3. Lithology of the Area Granetic / Schistose in nature

4. Tophographic Features of the Area The area was a plain land

5. Hydrogeological condition of the Area Belt

6. Geophysical survey result. By Diving method

   a) Type of Method.

   b) No of Soundings Conducted.

   c) Recommended Sounding.

   d) Particulars of formations present in the subsurface/possible ground water zones encountered at

Around 600'?
800-830'
1030-1050'
2
2

   e) Condition of Ground Water. Good

7. Type of well Recommended. Bore well (6½") -

8. Depth Recommended. 1000 - 1060' -

9. Expected Yield. 1400 - 1500 GPH -

10. Quality of Water. Good

11. Approximate depth at which the water is expected to be met. Around 600'?

12. Recommended Type and Length of casing to be inserted. nearly 150 - 170' of MS casing may be needed

13. Rain water Harvesting advised or not Strictly Advised -

14. Remarks.

Recommended point for Drilling

Shoshadri nagar Main Road

4th cross

Not to scale

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

4th result :-

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

To the Assistant Executive Engineer
BBMP
Dasarahalli Division

Date : 26.5.2014

1. Name of the Customer — MHR report

a) Village Ward No:- 14 2nd cross b) Block / Taluk. c) District Bangalore

2. Location.

3. Lithology of the Area — Granetic gneiss in nature

4. Tophographic Features of the Area — the area was a plain land

5. Hydrogeological condition of the Area — Good

6. Geophysical survey result. — By Diving method

   a) Type of Method.

   b) No of Soundings Conducted.

   c) Recommended Sounding.

   d) Particulars of formations present in the subsurface/possible ground water zones encountered at

Around 650' } 2
900-940' }
1050-1080' } 2

   e) Condition of Ground Water. — Good

7. Type of well Recommended. — Bore well (6½")

8. Depth Recommended. — 1150-1200'

9. Expected Yield. — 1300-1500 GPH

10. Quality of Water. — Good

11. Approximate depth at which the water is expected to be met. — Around 650'

12. Recommended Type and Length of casing to be inserted. — Nearly 20-25' of MS Casing may be needed

13. Rain water Harvesting adviced or not — Strictly Adviced

14. Remarks. — Recommended point for Drilling



Site Plan Map — Not to scale

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

5th point :-

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST

Phone :
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

To the Executive Engineer -
BBMP
Dasarahalli Sub Division -
NMH layout

Date : 26.5.2014

1. Name of the Customer

a) Village Work No:- 14 7th cross Road b) Block / Taluk. c) District Bangalore

2. Location. Granetic in nature -

3. Lithology of the Area

4. Tophographic Features of the Area The area was a plain land -

5. Hydrogeological condition of the Area Bellg -

6. Geophysical survey result. By Diving method -

   a) Type of Method.

   b) No of Soundings Conducted.

   c) Recommended Sounding.

   d) Particulars of formations present in the subsurface/possible ground water zones encountered at

Around 800'
970 - 1020'
1160 - 1180'
2
2

   e) Condition of Ground Water.

7. Type of well Recommended. Bellg
Bore well (6 1/3")
1200 - 1250'
1200 - 1500 GPH

8. Depth Recommended. Good -

9. Expected Yield.

10. Quality of Water.

ಖಾತರಿಯ ಪತ್ರವನ್ನು ಪಡೆಯಲಾಗಿದೆ
ಖಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಪಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073

Around 800'?

11. Approximate depth at which the water is expected to be met. Nearby 100 to 160 ft ms casing may be needed

12. Recommended Type and Length of casing to be inserted.

13. Rain water Harvesting adviced or not Strictly Advised -

14. Remarks.

Recommended point for Drilling

7th cross

Site Plan Map

Not to scale

Signature of the consultant

"WATER IS PRECIOUS, CONSERVE IT"

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref :

Date : 30.6.2014

YIELD REPORT

1. Name and Address of the Party : AEE WWd No 72 Dasarahalli Sub Division
2. Borewell Location : M.H.R Layout
3. Total Depth Drilled : 984 Feet
4. Casing Pipe : 147 Feet
5. Coupling : 10 Complete
6. Yield Details :
   a) First Spring Touched at : 390 Feet
   b) Second Spring Touched at : 590 Feet
   c) Third Spring Touched at : 890 Feet
7. Total Yield in G.P.H. : 1500 GPH
8. Remarks : Yields good

For **PALLAVI BOREWELL & DRILLERS**

M. B. Nirangaiah
Proprietor

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಾರ್ಯಾಲಯ
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಜೈಪತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref :

Date : 30.6.2014.....

YIELD REPORT

1. Name and Address of the Party : A.E.E Ward No 14 Dasarahalli Sub Division
2. Borewell Location : Sheshadri layout
3. Total Depth Drilled : 984 Feet
4. Casing Pipe : 147 Feet
5. Coupling : 16 Complete
6. Yield Details :
   a) First Spring Touched at : 420 Feet
   b) Second Spring Touched at : 680 Feet
   c) Third Spring Touched at : 940 Feet
7. Total Yield in G.P.H. : 1400 G.P.H
8. Remarks : Yield is Good

Ward No 14

For PALLAVI BOREWELL & DRILLERS

M.B. Nivargally

Proprietor

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ ಕಾರ್ಯಾಲಯ
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಪೀಣ್ಯಾ ಕೈಗಾರಿಕಾ ಪ್ರದೇಶ, ಬೆಂಗಳೂರು - 560 073

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* 30.6.2014

YIELD REPORT

1. Name and Address of the Party : AEE Ward No-14, Dasarahalli Sub Division.
2. Borewell Location : N.M.14 Layout
3. Total Depth Drilled : 984 Feet
4. Casing Pipe : 147 Feet
5. Coupling : 10 Coupling
6. Yield Details :
   a) First Spring Touched at : 340 Feet
   b) Second Spring Touched at : 530 Feet
   c) Third Spring Touched at : 980 Feet
7. Total Yield in G.P.H. : 1200 GPH
8. Remarks : Yield Good

Verified

ಬೆಂಗಳೂರು ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಜಲಮಂಡಳಿ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಜಲಮಂಡಳಿ, ಬೆಂಗಳೂರು - 560 073

For PALLAVI BOREWELL & DRILLERS

M B Nirabhavi

Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* 30.6.2014

YIELD REPORT

1. Name and Address of the Party : A.E.E Ward No. 14. Dasarahalli Sub Division
2. Borewell Location : Sampagi Ramiah layout
3. Total Depth Drilled : 984 Feet
4. Casing Pipe : 147 Feet
5. Coupling : 16 Couplys
6. Yield Details :
   a) First Spring Touched at : 420 Feet
   b) Second Spring Touched at : 645 Feet
   c) Third Spring Touched at : 790 Feet
7. Total Yield in G.P.H. : 1200 GPH
8. Remarks : Yield Good

For PALLAVI BOREWELL & DRILLERS

M.B Nivargi

Proprietor

ಕಿರಿಯ ಎಂಜಿನಿಯರ್ ಕಛೇರಿಯಲ್ಲಿ
೪೫. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಪಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073